

BUILDING SAFETY CERTIFICATE

NO.

Dated: 27/3/2023

Certified that existing building **Samarth Gurukul** (name of the building or premises) **At Bangarwadi, Belhe Tal:Junnar Dist:Pune Pin code :412410** (address) comprised of **Ground Floor** basement(s) and **First Floor** (upper floors) owned/occupied by **Samarth Gurukul, At Bangarwadi, Belhe Tal:Junnar Dist:Pune** (name of the institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Deputy Engineer (B & C) Z.P Work work Sub – Division Junnar (Pune)** (Name of Department Govt.) on **27/3/2023** (date of inspection) in the presence of **Mr. Vivek Vasantrao Shelke** (**Secretary Samarth Rural Educational Institutes , Samarth Gurukul** At Bangarwadi, Belhe Tal:Junnar Dist:Pune (name and addresses of the Manager/Secreatry or his representative) and that the building/premises is fit for occupancy upto classes **XII** (XI/XII) with effect from **27/3/2023** for a period of **2** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. **म. अ. उपायुक्त, पुणे**
2. **सा. म. बांध. / वसो. / 231**
3. **जुनर वि. 29/3/2023**
- 4.

Deputy Engineer, (B & C)
Z.P. Work Sub-Division Junnar

Issued on **27/3/2023** at **Junnar Z P Works Sub- Division Junnar**
by **Deputy Engineer (B&C) Z P Works Sub- Division Junnar Pune**

- Strike out whichever is not applicable

Signature with Seal : _____

Name : _____

Designation : _____

Name & Address of Department / Office : _____

(Assistant Engineer & above officer of concerned Govt.Department Only)

Note: This certificate should be signed/issued by Assistant Engineer & above officer of concerned Govt. Department only.

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.